

Supported GM Vehicles

[1996](#) [1997](#) [1998](#) [1999](#) [2000](#) [2001](#) [2002](#)

1996

Make	Model	Cable	Module Location
Buick	Riviera	02002888	Under RF seat
Buick	Skylark	02002888	Under RF seat
Chevrolet	Astro	02002888	Under LF seat
Chevrolet	Camaro	02002888	Under center console
Chevrolet	Cavalier	02002888	Under RF seat
Chevrolet	Express	02002888	Under LF seat
GMC	Safari	02002888	Under LF seat
GMC	Savana	02002888	Under LF seat
Oldsmobile	Achieva	02002888	Under RF seat
Oldsmobile	Aurora	02002888	Under RF seat
Pontiac	Firebird	02002888	Under center console
Pontiac	Grand AM	02002888	Under RF seat
Pontiac	Sunfire	02002888	Under RF seat
Saturn	All models	02002888	Under center console

1997

Make	Model	Cable	Module Location
Buick	Century	02002888	Under RF seat
Buick	LeSabre	02002888	Under RF seat
Buick	Park Avenue	02002888	Under RF seat
Buick	Regal	02002888	Under RF seat
Buick	Riviera	02002888	Under RF seat
Buick	Skylark	02002888	Under RF seat
Cadillac	Commercial Special	02002828	Under LF seat
Cadillac	Deville	02002828	Under LF seat
Cadillac	Eldorado	02002828	Under LF seat
Cadillac	Seville	02002828	Under LF seat
Chevrolet	Astro	02002888	Under LF seat
Chevrolet	Camaro	02002888	Under center console
Chevrolet	Cavalier	02002888	Under RF seat
Chevrolet	Corvette	02002888	Behind accessory trim plate, under heater and AC control head

Chevrolet	Express	02002888	Under LF seat
Chevrolet	Lumina	02002888	Under RF seat
Chevrolet	Malibu	02002888	Under RF seat
Chevrolet	Monte Carlo	02002888	Under RF seat
Chevrolet	S10	02002888	Under center console
Chevrolet	Silverado	02002888	Under LF seat
Chevrolet	Suburban	02002888	Under LF seat
Chevrolet	Tahoe	02002888	Under LF seat
Chevrolet	Venture	02002888	Under RF seat
GM1	EV1	02002888	RF side of battery pack tunnel near IP
GMC	Safari	02002888	Under LF seat
GMC	Savana	02002888	Under LF seat
GMC	Sierra	02002888	Under LF seat
GMC	Yukon	02002888	Under LF seat
Oldsmobile	Achieva	02002888	Under RF seat
Oldsmobile	Aurora	02002888	Under RF seat
Oldsmobile	Eighty Eight	02002888	Under RF seat
Oldsmobile	Regency	02002888	Under RF seat
Oldsmobile	Silhouette	02002888	Under RF seat
Pontiac	Bonneville	02002888	Under RF seat
Pontiac	Firebird	02002888	Under center console
Pontiac	Grand AM	02002888	Under RF seat
Pontiac	Grand Prix	02002888	Under RF seat
Pontiac	Sunfire	02002888	Under RF seat
Pontiac	Trans Sport	02002888	Under RF seat
Saturn	All models	02002888	Under center console

1998

Make	Model	Cable	Module Location
Buick	Century	02002888	Under RF seat
Buick	LeSabre	02002888	Under RF seat
Buick	Park Avenue	02002828	Under RF seat
Buick	Regal	02002888	Under RF seat
Buick	Riviera	02002888	Under RF seat
Buick	Skylark	02002888	Under RF seat
Cadillac	Commercial Special	02002828	Under LF seat
Cadillac	Deville	02002828	Under LF seat
Cadillac	Eldorado	02002828	Under RF seat
Cadillac	Seville	02002828	Under RF seat
Chevrolet	Astro	02002888	Under LF seat

Chevrolet	Blazer	02002888	Under center console
Chevrolet	Camaro	02002888	Under center console
Chevrolet	Cavalier	02002888	Under RF seat
Chevrolet	Corvette	02002888	Behind accessory trim plate, under heater and AC control head
Chevrolet	Express	02002888	Under LF seat
Chevrolet	Malibu	02002888	Under RF seat
Chevrolet	Monte Carlo	02002888	Under RF seat
Chevrolet	Lumina	02002888	Under RF seat
Chevrolet	S10	02002888	Under center console
Chevrolet	S10 electric	02002888	Under center console
Chevrolet	Silverado	02002888	Under LF seat
Chevrolet	Suburban	02002888	Under LF seat
Chevrolet	Tahoe	02002888	Under LF seat
GMC	Jimmy	02002888	Under center console
GMC	Safari	02002888	Under LF seat
GMC	Savana	02002888	Under LF seat
GMC	Sierra	02002888	Under LF seat
GMC	Sonoma	02002888	Under center console
GMC	Yukon	02002888	Under LF seat
Oldsmobile	Achieva	02002888	Under RF seat
Oldsmobile	Aurora	02002888	Under RF seat
Oldsmobile	Bravada	02002888	Under center console
Oldsmobile	Cutlass	02002888	Under RF seat
Oldsmobile	Eighty Eight	02002888	Under RF seat
Oldsmobile	Intrigue	02002888	Under RF seat
Pontiac	Bonneville	02002888	Under RF seat
Pontiac	Firebird	02002888	Under center console
Pontiac	Grand AM	02002888	Under RF seat
Pontiac	Grand Prix	02002888	Under RF seat
Pontiac	Sunfire	02002888	Under RF seat
Saturn	All models	02002888	Under center console

1999

Make	Model	Cable	Module Location
Buick	Century	02002829	Under RF seat
Buick	Le Sabre	02002888	Under RF seat
Buick	Park Avenue	02002828	Under RF seat
Buick	Regal	02002829	Under RF seat
Buick	Riveria	02002888	Under RF seat
Cadillac	Commercial Special	02002828	Under LF seat

Cadillac	Deville	02002828	Under LF seat
Cadillac	Eldorado	02002828	Under LF seat
Cadillac	Escalade	02002888	Under LF seat
Cadillac	Seville	02002828	Under RF seat
Chevrolet	Astro	02002888	Under LF seat
Chevrolet	Blazer	02002888	Under center console
Chevrolet	Camaro	02002829	Under center console
Chevrolet	Cavalier	02002888	Under RF seat
Chevrolet	Corvette	02002829	Behind accessory trim plate, under heater and AC control head
Chevrolet	Express	02002888	Under LF seat
Chevrolet	Lumina	02002888	Under RF seat
Chevrolet	Malibu	02002888	Under RF seat
Chevrolet	Monte Carlo	02002888	Under RF seat
Chevrolet	S10	02002888	Under center console
Chevrolet	S10 Electric	02002888	Under center console
Chevrolet	Silverado	02002888	Under LF seat
Chevrolet	Suburban	02002888	Under LF seat
Chevrolet	Tahoe	02002888	Under LF seat
GM ₁	EV1	02002888	RF side of battery pack tunnel, near IP
GMC	Jimmy	02002888	Under center console
GMC	Safari	02002888	Under LF seat
GMC	Savana	02002888	Under LF seat
GMC	Sierra	02002888	Under LF seat
GMC	Sonoma	02002888	Under center console
GMC	Yukon	02002888	Under LF seat
Oldsmobile	Alero	02002888	Under RF seat
Oldsmobile	Aurora	02002888	Under RF seat
Oldsmobile	Bravada	02002888	Under center console
Oldsmobile	Cutlass	02002888	Under RF seat
Oldsmobile	Eighty Eight	02002888	Under RF seat
Oldsmobile	Intrigue	02002888	Under RF seat
Pontiac	Bonneville	02002888	Under RF seat
Pontiac	Firebird	02002829	Under center console
Pontiac	Grand AM	02002888	Under RF seat
Pontiac	Grand Prix ₂	02002829	Under RF seat
Pontiac	Sunfire	02002888	Under RF seat
Saturn ₃	All Models ₂	02002829	Under center console

Make	Model	Cable	Module Location
Buick	Century	02002829	Under RF seat
Buick	LeSabre	02002829	Under center console
Buick	Park Avenue	02002829	Under center console
Buick	Regal	02002829	Under RF seat
Cadillac	Commercial Special	02002829	Under center console
Cadillac	Deville	02002829	Under center console
Cadillac	Eldorado	02002828	Under LF seat
Cadillac	Escalade	02002888	Under LF seat
Cadillac	Seville	02002829	Under RF seat
Chevrolet	Astro	02002829	Under LF seat
Chevrolet	Blazer	02002829	Under center console
Chevrolet	Camaro	02002829	Under center console
Chevrolet	Cavalier	02002829	Under RF seat
Chevrolet	Corvette	02002829	Behind accessory trim plate, under heater and AC control head
Chevrolet	Express	02002888	Under LF seat
Chevrolet	Impala	02002829	Under RF seat
Chevrolet	Lumina	02002888	Under RF seat
Chevrolet	Malibu	02002829	Under RF seat
Chevrolet	Monte Carlo	02002829	Under RF seat
Chevrolet	S10	02002829	Under center console
Chevrolet	Silverado	02002829	Under LF seat
Chevrolet4	Silverado	02002888	Under LF seat
Chevrolet	Suburban	02002829	Under LF seat
Chevrolet4	Suburban	02002888	Under LF seat
Chevrolet	Tahoe	02002829	Under LF seat
Chevrolet4	Tahoe	02002888	Under LF seat
Chevrolet	Venture	02002829	Under RF seat
GMC	Jimmy	02002829	Under center console
GMC	Safari	02002829	Under LF seat
GMC	Savana	02002888	Under LF seat
GMC	Sierra	02002829	Under LF seat
GMC4	Sierra	02002888	Under LF seat
GMC	Sonoma	02002829	Under center console
GMC	Yukon	02002829	Under LF seat
GMC4	Yukon	02002888	Under LF seat
Isuzu	Hombre	02002829	Under center console
Oldsmobile	Alero	02002829	Under RF seat
Oldsmobile	Bravada	02002829	Under center console
Oldsmobile	Intrigue	02002829	Under RF seat
Oldsmobile	Silhouette	02002829	Under RF seat

Pontiac	Bonneville	02002829	Under center console
Pontiac	Firebird	02002829	Under center console
Pontiac	Grand Am	02002829	Under RF seat
Pontiac	Grand Prix ²	02002829	Under RF seat
Pontiac	Montana	02002829	Under RF seat
Pontiac	Sunfire	02002829	Under RF seat
Saturn	All but LS	02002829	Under center console

2001

Make	Model	Cable	Module Location
Buick	Century	02002829	Under RF seat
Buick	LeSabre	02002829	Under center console
Buick	Park Avenue	02002829	Under center console
Buick	Regal	02002829	Under RF seat
Buick	Rendezvous	02002829	Under RF seat
Cadillac	Commercial Special	02002829	Under center console
Cadillac	Deville	02002829	Under center console
Cadillac	Eldorado	02002828	Under LF seat
Cadillac	Escalade	02002829	Under LF seat
Cadillac	Seville	02002829	Under RF seat
Chevrolet	Astro	02002829	Under LF seat
Chevrolet	Blazer	02002829	Under center console
Chevrolet	Camaro	02002829	Under center console
Chevrolet	Cavalier	02002829	Under RF seat
Chevrolet	Corvette	02002829	Behind accessory trim plate, under heater and AC control head
Chevrolet	Express ²	02002829	Under LF seat
Chevrolet	Impala	02002829	Under RF seat
Chevrolet	Lumina	02002888	Under RF seat
Chevrolet	Malibu	02002829	Under RF seat
Chevrolet	Monte Carlo	02002829	Under RF seat
Chevrolet	S10	02002829	Under center console
Chevrolet	Silverado	02002829	Under LF seat
Chevrolet	Suburban	02002829	Under LF seat
Chevrolet	Tahoe	02002829	Under LF seat
Chevrolet	Venture	02002829	Under RF seat
GMC	Jimmy	02002829	Under center console
GMC	Safari	02002829	Under LF seat
GMC	Savanaz	02002829	Under LF seat
GMC	Sierra	02002829	Under LF seat
GMC	Sonoma	02002829	Under center console
GMC	Yukon	02002829	Under LF seat

Isuzu	Hombre	02002829	Under center console
Oldsmobile	Alero	02002829	Under RF seat
Oldsmobile	Aurora	02002829	Under center console
Oldsmobile	Bravada	02002829	Under center console
Oldsmobile	Intrigue	02002829	Under RF seat
Oldsmobile	Silhouette	02002829	Under RF seat
Pontiac	Aztek	02002829	Under RF seat
Pontiac	Bonneville	02002829	Under center console
Pontiac	Firebird	02002829	Under center console
Pontiac	Grand Am	02002829	Under RF seat
Pontiac	Grand Prix ²	02002829	Under RF seat
Pontiac	Montana	02002829	Under RF seat
Pontiac	Sunfire	02002829	Under RF seat
Saturn	All but LS	02002829	Under center console

2002

Make	Model	Cable	Module Location
Buick	Century	02002829	Under RF seat
Buick	LeSabre	02002829	Under center console
Buick	Park Avenue	02002829	Under center console
Buick	Regal	02002829	Under RF seat
Buick	Rendezvous	02002829	Under RF seat
Cadillacs	Commercial Special		Under center console
Cadillacs	Deville		
Cadillac	Escalade	02002829	Under LF seat
Cadillac	Seville	02002829	Under RF seat
Chevrolet	Avalanche	02002829	Under center console
Chevrolet	Astro	02002829	Under LF seat
Chevrolet	Blazer	02002829	Under center console
Chevrolet	Camaro	02002829	Under center console
Chevrolet	Cavalier	02002829	Under RF seat
Chevrolet	Corvette	02002829	Behind accessory trim plate, under heater and AC control head
Chevrolet	Express ²	02002829	Under LF seat
Chevrolet	Impala	02002829	Under RF seat
Chevrolet	Malibu	02002829	Under RF seat
Chevrolet	S10	02002829	Under center console
Chevrolet	Silverado	02002829	Under LF seat
Chevrolet	Suburban	02002829	Under LF seat
Chevrolet	Tahoe	02002829	Under LF seat

Chevrolet Chevrolets	TrailBlazer Venture	02002829	Under center console Under RF seat
GMC	Envoy	02002829	Under center console
GMC	Safari	02002829	Under LF seat
GMC	Savanaz	02002829	Under LF seat
GMC	Sierra	02002829	Under LF seat
GMC	Sonoma	02002829	Under center console
GMC	Yukon	02002829	Under LF seat
Isuzu	Hombre	02002829	Under center console
Oldsmobile	Alero	02002829	Under RF seat
Oldsmobile	Aurora	02002829	Under center console
Oldsmobile	Bravada	02002829	Under center console
Oldsmobile	Intrigue	02002829	Under RF seat
Oldsmobiles	Silhouette		Under RF seat
Pontiac	Aztek	02002829	Under RF seat
Pontiac	Bonneville	02002829	Under center console
Pontiac	Firebird	02002829	Under center console
Pontiac	Grand Am	02002829	Under RF seat
Pontiac	Grand Prix ²	02002829	Under RF seat
Pontiacs	Montana		Under RF seat
Pontiac	Sunfire	02002829	Under RF seat
Saturn	All cars except LS	02002829	Under center console
Saturn	VUE		Under RF seat

1. Please connect directly to the SDM for EV1 electric cars.
2. Does not record pre-crash data.
3. 1999 Saturn vehicle's DLC port has a non-standard wiring configuration and does not interface with the Vetronix OBD II interface cable (02002837). Please connect directly to the SDM, or contact Vetronix for more information.
4. These trucks have different SDMs depending upon body style. If the eighth digit of the VIN is either F, J, or R, please use the **02002888** cable.
5. Please connect directly to the vehicle's DLC. There is no SDM interface cable available for this vehicle at this time. Please contact Vetronix technical support for more information.